

Service Instruction		
1. General		
(a) No:	SI.001	
(b) Revision / Date	Revision 1 – 25 th May 2012	
(b) Title	Internal Lighting System Upgrade	
(c) Description	As part of on going improvements to the Hiflyer system, the internal lighting system has been upgraded to an LED system.	
(d) Applicability	LTL Hiflyer 203T	
(e) Effectivity	All Hiflyer systems HF001 and subsequent	
2. Accomplishment Instructions Clients wishing to have the LED lighting system integrated into their Hiflyer should contact Lindstrand Technologies		
3. Materials n/a		
4. Other publications Affected TAOM or TAFM		
5. Remarks None		
Complied by: 		Notes:
Date 25/05/2012	Name Lee Barnfield	
6. Design Organisation Approval		
Approval Statement		
<p>I hereby confirm that these instructions are in compliance with all the applicable airworthiness requirements. The technical content of this document is approved under the authority of DOA nr EASA.21J.176</p> <p>Signed, for and on behalf of Lindstrand Technologies Ltd</p> 		
Head of Design Organisation		
Date 25/05/2012	Name Per Lindstrand	